

SWITCHES

SLIDING LEVER



18-113 SPST
ON - OFF
1 amp.
125 VAC



18-332 SPST
ON - OFF
4 amp.
125 VAC



18-335 SPST
OFF - MOM. ON
6 amp.
125 VAC




S-60-B SPDT
ON - ON
4 amp.
125 VAC



18-145 DPST
ON - OFF
3 amp.
125 VAC




18-242 SP3T
ON - ON - ON
3 amp.
125 VAC



18-139 DPDT
ON - ON
4 amp.
125 VAC



S-316-A DPDT
ON - ON
3 amp.
125 VAC



18-387 SPST
OFF - MOM. ON
S-60-A
ON - OFF
4 amp. 125 volt



80220 SPST
ON - OFF
8 amp.
125 VAC




18-234 SPST
ON - OFF
with speed control
125 VAC



81550 SPST
ON - OFF
feed through
15 amp. 125 VAC



FA423
4-6A 250V



81805A SPST
ON - OFF
6 amp.
125 VAC



81145C DPST
ON - OFF
6 amp.
125 VAC

EURTON ELECTRIC CO., INC.
9920 PAINTER AVE., P.O. BOX 2113
SANTA FE SPRINGS CA 90670

800-423-4789
fax 562-946-0014
www.eurtonelectric.com

SWITCHES


SLIDING LEVER



FU206
DPDT
4A 250V




FU201
DPDT
4A 250V



18-122 SPST
ON - OFF
6 amp.
125 VAC




FU210
DPDT
4A 250V



FU202
DPDT
4A 250V



18-317 SPST
ON - OFF
10 amp.
125 VAC




FU211
DPDT
4A 250V



FU205
DPDT
4A 250V




FU212
DPDT
4A 250V



FU205A
DPDT
4A 250V



18-131RB SPST
HI - LO
6 amp.
125 VAC




18-409 DPST
ON - OFF
speed control
6 amp. 125 volt



18-362 DPST
ON - OFF
SPEED CONTROL
6 amp. 125 VAC



18-131YB SPST
HI - LO
6 amp.
125 VAC



18-420 DPST
ON - OFF
speed control
3 amp. 250 volt

EURTON ELECTRIC CO., INC.
9920 PAINTER AVE., P.O. BOX 2113
SANTA FE SPRINGS CA 90670

800-423-4789
fax 562-946-0014
www.eurtonelectric.com