

SWITCHES

PUSH BUTTON 3/4, 1, 3, 6, 10, & 15 AMP



8406K1
ON - MOM. OFF
3/4 amp.
125 volt



8410K1
ON - MOM. OFF
8410K3
OFF - MOM. ON
3/4 amp.
125 volt



8411K7
ON - MOM. OFF
8411K12
OFF - MOM. ON
3/4 amp.
125 volt



3392
MOMENTARY
2 CIRCUIT
1 CIRCUIT NORM. ON
1 CIRCUIT NORM. OFF
1 amp.
125 volt



80512E
OFF - MOM. ON
3 amp.
125 volt



8440K2
OFF - MOM. ON
3 amp.
125 volt



8440K3
OFF - MOM. ON
3 amp.
125 volt



112-PAM SPDT
ON - ON
3 amp.
125 volt



80541ER
OFF - MOM. ON
3 amp.
125 volt



18-251
PUSH ON - PUSH OFF
6 amp.
125 volt



7208K4
PUSH ON - PUSH OFF
6 amp.
125 volt



170
ON - MOM. OFF
172
OFF - MOM. ON
10 amp. 250 volt
15 amp. 125 volt



8444k4
OFF - MOM. ON
15 amp.
125 volt

EURTON ELECTRIC CO., INC.
9920 PAINTER AVE., P.O. BOX 2113
SANTA FE SPRINGS CA 90670

800-423-4789
fax 562-946-0014
www.eurtonelectric.com

SWITCHES

PUSH BUTTON 16, 20, 30, & 75 AMP




80938 DPST
OFF - MOM. ON

80938F DPST
ON - MOM. OFF
20 amp.
125 volt




80863 DPST
PUSH ON - PUSH OFF
16 amp.
125 volt



82321 DPST
OFF - MOM. ON
20 amp.
125 volt



505078 DPST
OFF - MOM. ON
20 amp.
125 volt



80140-C DPST
OFF - MOM. ON
30 amp.
250 volt



2302
PUSH - PULL
75 amp.
6 - 28 VDC

EURTON ELECTRIC CO., INC.
9920 PAINTER AVE., P.O. BOX 2113
SANTA FE SPRINGS CA 90670

800-423-4789
fax 562-946-0014
www.eurtonelectric.com

SWITCHES

PUSH BUTTON



FA351
on-off
10A 250V



FA334
SPST
5A 250V




FA334A
SPST
5A 250V



FA334B
SPST
5A 250V

MOTOR REWINDING!!



BEARINGS



BRUSHES



CAPACITORS




CORD SETS



PLUGS & CONNECTORS



TERMINALS



EURTON ELECTRIC CO., INC.
9920 PAINTER AVE., P.O. BOX 2113
SANTA FE SPRINGS CA 90670

800-423-4789
fax 562-946-0014
www.eurtonelectric.com