

# SWITCHES

## TOGGLE 3 & 6 AMP

### TOGGLE 3 & 6 amp



**18-260**  
ON - OFF  
3 amp.  
125 volt



**81054 H**  
MOM. ON  
DPST 3A  
250 volt



**83052 CG**  
ON - ON  
SPDT 3A  
125 volt



**8964 KC**  
ON - OFF  
SPST 3A  
250 volt



**20905 C**  
ON - OFF  
DPST 3A  
125 volt



**8371K7**  
ON - OFF  
DPST 3A  
250 volt



**8280K16**  
ON - OFF  
3 amp.  
250 volt



**8290K15**  
ON - OFF  
3 amp.  
250 volt



**8290K16**  
ON - OFF  
3 amp.  
250 volt



**38099BD**  
ON - ON  
DPDT 3A  
250 volt



**8297K8**  
ON - ON  
SPDT 3A  
125 volt



**18-22**  
MOM. - ON  
6 amp.  
125 volt



**82145 UA**  
ON - ON  
DPDT 6A  
125 volt



**8396K8**  
ON - OFF  
6 amp.  
125 volt



**8391K8**  
ON - OFF  
6 amp.  
125 volt



**8381K8**  
ON - OFF  
6 amp.  
125 volt



**8375K7**  
ON - ON  
DPDT 6A  
125 volt



**8373K7**  
ON - ON  
DPDT 6A  
125 volt



**8374K7**  
ON - ON  
DPDT 6A  
125 volt




**8302K5**  
ON - OFF  
**8301K5**  
MOM. - ON  
6 amp.  
125 volt

**EURTON ELECTRIC CO., INC.**  
9920 PAINTER AVE., P.O. BOX 2113  
SANTA FE SPRINGS CA 90670

**800-423-4789**  
fax 562-946-0014  
www.eurtonelectric.com

# SWITCHES

## TOGGLE 8,10,14 & 17 AMP



**18-322**  
ON - OFF  
8 amp.  
125 volt




**353K1**  
OFF - ON 1 CIRCUIT -  
MOM. ON 2 CIRCUITS  
8 amp.  
125 volt



**7566K5 DPST**  
MOM. ON  
17 amp. 125 volt  
12 amp. 250 volt



**8690K2 DPDT**  
ON - ON  
10 amp.  
250 volt



**160 A**  
ON - OFF  
10 amp.  
125 volt



**160 B**  
ON - OFF  
10 amp.  
125 volt



**160 C**  
ON - OFF  
10 amp.  
125 volt



**80983 3PDT**  
ON - OFF - ON  
10 amp.  
125 volt



**80638 D DPDT**  
ON - OFF - ON  
14 amp.  
125 volt

**EURTON ELECTRIC CO., INC.**  
9920 PAINTER AVE., P.O. BOX 2113  
SANTA FE SPRINGS CA 90670

**800-423-4789**  
fax 562-946-0014  
[www.eurtonelectric.com](http://www.eurtonelectric.com)

# SWITCHES

## TOGGLE 15 AMP



**7500K14 SPST**  
ON - OFF  
**7506K4**  
OFF - MOM. ON  
**6FA58**  
ON - MOM. OFF  
15 amp.



**7501K15 SPST**  
ON - OFF  
15 amp.  
125 volt



**7501K13 SPST**  
ON - OFF  
15 amp.  
125 volt



**7502K13 SPDT**  
ON - OFF - ON  
**7504K4**  
ON - ON  
**7509K5 SPDT**  
MOM. ON - OFF - MOM. ON



**7503K15 SPDT**  
ON - OFF - ON  
15 amp.  
125 volt



**7503K13 SPDT**  
ON - OFF - ON  
15 amp.  
125 volt



**7560K5 DPST**  
ON - OFF  
15 amp.  
125 volt



**7561K6 DPST**  
ON - OFF  
15 amp.  
125 volt



**7561K4 DPST**  
ON - OFF  
15 amp.  
125 volt



**7565K7 DPDT**  
ON - ON  
**7563K6 DPDT**  
ON - OFF - ON  
15 amp.  
125 volt



**7562K4 DPDT**  
ON - OFF - ON  
**7564K6 DPDT**  
ON - ON  
**7570K5 DPDT**  
ON - MOM. ON  
**7568K2**  
ON - OFF - MOM. ON  
**7569K2 DPDT**  
MOM. ON - OFF - MOM. ON  
15 amp.



**7563K4 DPDT**  
ON - OFF - ON  
**7565K5 DPDT**  
ON - ON  
15 amp.  
125 volt

**EURTON ELECTRIC CO., INC.**  
9920 PAINTER AVE., P.O. BOX 2113  
SANTA FE SPRINGS CA 90670

**800-423-4789**  
fax 562-946-0014  
[www.eurtonelectric.com](http://www.eurtonelectric.com)

# SWITCHES

## TOGGLE 15 AMP



**7692K13 4PDT**  
ON - OFF - ON  
15 amp.  
125 volt



**7700K2 3PST**  
ON - OFF  
15 amp.  
125 volt



**7701K1 3PDT**  
ON - OFF - ON  
15 amp.  
125 volt



**7701K2 3PDT**  
ON - OFF - ON  
**7991K10**  
ON - POS. OFF - ON  
15amp.



**7701K3 3PDT**  
ON - OFF - ON  
15 amp.  
125 volt



**7702K2 3PDT**  
ON - ON  
15 amp.  
125 volt




**HM25B-73 3PDT**  
ON - OFF - MOM. ON  
15amp.  
125 volt




**HM25E-73 3PDT**  
ON - OFF - MOM. ON  
15amp.  
125 volt



**7691K14 4PST**  
ON - OFF  
15 amp.  
125 volt



**1276R DPDT**  
ON - OFF - ON  
15 amp.  
125 volt



**6G053 DPDT**  
MOM. ON - OFF - MOM. ON  
15 amp.  
125 volt

**EURTON ELECTRIC CO., INC.**  
9920 PAINTER AVE., P.O. BOX 2113  
SANTA FE SPRINGS CA 90670

**800-423-4789**  
fax 562-946-0014  
[www.eurtonelectric.com](http://www.eurtonelectric.com)

# SWITCHES


## TOGGLE 16 & 20 AMP



**7320K3 DPST**  
ON - OFF  
16 amp.  
125 volt



**7360K8 DPST**  
ON - OFF  
20 amp.  
125 volt



**80600 DPST**  
ON - OFF  
16 amp.  
125 volt



**80600B DPST**  
ON - OFF  
16 amp.  
125 volt



**3032-SW DPST**  
ON - OFF  
30 amp.

**2222-SW DPST**  
20 amp.

125 - 277 VAC  
**6808-UDAC**  
20 amp. 600 volt



**8909K280 DPST**  
ON - OFF  
16 amp.  
125 volt

**EURTON ELECTRIC CO., INC.**  
9920 PAINTER AVE., P.O. BOX 2113  
SANTA FE SPRINGS CA 90670

**800-423-4789**  
fax 562-946-0014  
[www.eurtonelectric.com](http://www.eurtonelectric.com)

# SWITCHES

## TOGGLE 20 AMP



**7802K31 SPST**  
ON - OFF  
20 amp.  
125 volt



**7802K21 SPST**  
ON - OFF  
20 amp.  
125 volt



**7802K22 SPDT**  
ON - OFF - ON  
20 amp.  
125 volt



**7803K12 DPDT**  
ON - OFF - ON  
20 amp.  
125 volt



**7802K32 SPDT**  
ON - OFF - ON  
**7802K35 SPDT**  
ON - MOM. ON  
20 amp.  
125 volt



**7803K31 DPST**  
ON - OFF  
20 amp.  
125 volt



**7803K21 DPST**  
ON - OFF  
20 amp.  
125 volt



**7803K22 DPDT**  
ON - OFF - ON  
**7803K23 DPDT**  
ON- ON  
20 amp.  
125 volt



**7803K32 DPDT**  
ON - OFF - ON  
**7803K33 DPDT**  
ON- ON  
**7803K37 DPDT**  
MOM. ON - OFF - MOM. ON  
20 amp.  
125 volt

**EURTON ELECTRIC CO., INC.**  
9920 PAINTER AVE., P.O. BOX 2113  
SANTA FE SPRINGS CA 90670

**800-423-4789**  
fax 562-946-0014  
[www.eurtonelectric.com](http://www.eurtonelectric.com)

# SWITCHES

## TOGGLE 20 AMP 125 & 250 volt



**80634 DPDT**  
**ON - OFF - ON**  
 20 amp. 125 volt  
**80988 DPDT**  
 30 amp 125 volt



**80421U DPST**  
**ON - OFF**  
 20 amp.  
 250 volt



**80602F DPST**  
**ON - OFF**  
 20 amp.  
 125 volt



**80602 DPST**  
**ON - OFF**  
 20 amp.  
 125 volt



**80602FJ DPST**  
**ON - OFF**  
 20 amp.  
 125 volt



**8320K1 3PST**  
**ON - OFF**  
 20 amp.  
 250 volt



**80617 FR**  
**MOM. - ON**  
 20 amp.  
 125 volt

**EURTON ELECTRIC CO., INC.**  
 9920 PAINTER AVE., P.O. BOX 2113  
 SANTA FE SPRINGS CA 90670

**800-423-4789**  
 fax 562-946-0014  
[www.eurtonelectric.com](http://www.eurtonelectric.com)

# SWITCHES

## TOGGLE 30 & 60 AMP



**80898 3PDT**  
ON - OFF - ON  
30 amp. 125 volt  
20 amp 250 volt



**80899 4PDT**  
ON - OFF - ON  
30 amp. 125 volt  
20 amp 250 volt



**80988 EAR DPDT**  
ON - OFF - ON  
30 amp. 125 volt  
20 amp. 250 volt



**7576K2 SPST**  
ON - OFF  
30 amp. 125 volt  
25 amp. 250 volt



**MC240L 2PST**  
40 amp. 600 volt 1 ph  
**MC260L 2PST**  
60 amp. 600 volt 1 ph  
**MC340L 3PST**  
40 amp. 600 volt 3 ph  
**MC360L 3PST**  
60 amp. 600 volt 3 ph  
ON - OFF



**7810 U 3PST 3 ph**  
30 amp. 600 volt  
**6810 U DPST**  
30A 250 20A 600  
ON - OFF



**80404 3PST**  
ON - OFF  
3 PHASE  
30 amp. 250 volt  
20 amp 600 volt



**3032-SW DPST**  
ON - OFF  
30 amp.  
**2222-SW DPST**  
20 amp.  
125 - 277 VAC  
**6808 UDAC**  
20 amp. 600 volt



**100006 ZA DPST**  
ON - OFF  
30 amp.  
250 volt



**100006 DPST**  
ON - OFF  
30 amp.  
250 volt



**6808 U DPST**  
**8808 U 4PST**  
ON - OFF  
30 amp. 250 volt  
20 amp. 600 volt



**8684 U SPST**  
ON - OFF  
30 amp.  
250 volt

**EURTON ELECTRIC CO., INC.**  
9920 PAINTER AVE., P.O. BOX 2113  
SANTA FE SPRINGS CA 90670

**800-423-4789**  
fax 562-946-0014  
[www.eurtonelectric.com](http://www.eurtonelectric.com)